: OUTLET WELDMENT ASSEMBLY

Date:

Monday, 28/04/2008 8:13:23 AM

User:

Julie Lecocq

**Process Sheet** 

Customer

: CU-DAR001 Dart Helicopters Services

**Job Number** 

: 38809

**Estimate Number** 

: 11839

P.O. Number

Previous Run

Prsht Rev.

Written By

: 28/04/2008

This Issue

: NC

: // First Issue

Type

S.O. No. :

: LARGE FAB ASSY

**Part Number** 

**Drawing Name** 

: D2319

**Drawing Number** 

: D2319 REV B

**Project Number Drawing Revision** 

: N/A

Material

**Due Date** 

: 15/05/2008

Qty:

4 Um:

Each

Checked & Approved By

Comment

: Est:

05.03.29

New Issue KJ/JLM

**Additional Product** 

Job Number:



Seq. #:

**Machine Or Operation:** 

Description:

D22913

Heater Tube 4"



Comment: Qty.:

1.0000 Each(s)/Unit Total: 4.0000 Each(s)

Heater Tube 4"

Qty Part Number

Description

4" Heater Tube

2.0

1 D2288

Heater Support



D22913

Comment: Qty.: 1.0000 Each(s)/Unit

Total: 4.0000 Each(s)



Pick:

**Qty Part Number** 

Description Batch

D2288


**Heater Support** 

D2293





1.0000 Each(s)/Unit Total: 4.0000 Each(s)



D2293

Pick:

Qty

Part Number Description

6" Heater Tube

LARGE FAB 1 4.0

LARGE FABRICATION RESOURCE 1



Comment: LARGE FABRICATION RESOURCE 1

Assemble and Weld as per Dwg D2319





## **Dart Aerospace Ltd**

W/O:			WC	ORK ORDER CHANG	GES			1	
DATE STEP		PROCEDURE CHANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
,								:	
						· ·		:	
Part No	•	PAR #:	Fault Cate	gory:	NCR: Yes	No <b>DQA</b>	:	_ Date: _	
							:	Date:	
NCR:			WORK ORDI	ER NON-CONFORM	ANCE (NCR	2)			· **
DATE	STEP	Description of NC	Corrective Action Section B			Verification		Approval	Approval
DAIL	J. J.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section	n C	Chief Eng	QC Inspector
			#?					d 1	
							ı	;	
								1	

NOTE: Date & initial all entries

Date: Monday, 28/04/2008 8:13:23 AM User: Julie Lecocq **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: OUTLET WELDMENT ASSEMBLY Job Number: 38809 Part Number: D2319 Job Number: Seq. #: **Machine Or Operation:** Description: VISUAL WELDING INSPECTION 5.0 QC9 (4) **Comment: VISUAL WELDING INSPECTION** QC5 6.0 INSPECT WORK TO CURRENT STEP Comment: INSPECT WORK TO CURRENT STEP 7.0 PACKAGING 1 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: 8.0 QC21 08/07/25 95/ MF 08-07-24 Comment: FINAL INSPECTION/W/O RELEASE Job Completion

## **Dart Aerospace Ltd**

W/O:		WORK ORDER CHA				,	
DATE STEP		PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							-
						,	
			\$			'	
						ı	
				··· · · · · · · · · · · · · · · · · ·			
Part No	• •	PAR #: Fault Category:	NCR: Yes	No <b>DQ</b>	<b>4</b> :	Date:	

QA: N/C Closed: \_\_\_\_ Date: \_\_

NCR:	,	WORK ORDER NON-CONFORMANCE (NCR)							
	STEP	Description of NC	Corrective Action Section B			Verification			
DATE		Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector	
						:	1		
							1		
							i		

NOTE: Date & initial all entries





1	Williams	DART AERO ACCESSORIES VICTORIA INTERNATIONAL AIRPORT, CANADA	INC
CHEC			REV. B
13	4 6	D2319 SHEET	1 OF 2
DATE		TITLE	SCALE
Jar	. 10, 1995	OUTLET WELDMENT ASSEMBLY	
В	96:04:18	MODIFIED MASTER PARTS LIST	


QTY	Part No.	Description
X	D2319	OUTLET WELDMENT ASSEMBLY
1	D2291-3	4" RING
1	D2293	6" RING
1	D2288	END PLATE

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 3 2007





PREPARED  B. William	ns .	DART AERO ACCESSO VICTORIA INTERNATIONAL AIRPORT	
CHECKED	APPROVED		REV. B
BW		D2319	SHEET 2 OF 2
DATE		TITLE	SCALE
Jan. 10.	1995	OUTLET WELDMENT ASSEMBLE	<b>~</b>



Copyright 1995 by DART AERO ACCESSORIES INC